

BridgeMaster E EPA(L) Version SC1.03 Software Release

This is to inform you that BridgeMaster E EPA(L) software version SC1.03 has been released from the software department.

The main reason for this software upgrade is to allow a 15-inch LCD display to be used without incorrectly indicating it as a 340 interlaced monitor on the System Status menu.

In addition, in line with changes made in BM E version 5.01, we have

- **Provided feedback to the operator when the EEPROM is detected as corrupt: "Warning - Radar requires re-commissioning"**
- **Changed the default heading marker offset to 350 degrees**
- **Advised the operator to read the manual when the radar is in standby**

There are no changes to the external interfaces.