

**Product: Decca BridgeMaster E Series Radars**

**Subject: General Information 3**

### **1. Motor Drive PCB (65801811) and Scanner Motor & Gearbox (91003765)**

It is recommended that whenever a failure of either of these components is encountered, both components are replaced at the same time.

### **2. Software releases applicability**

The C4.08 release applies to the following systems:

- Commercial ARPA
- Single Channel VISION Display (ATA & ARPA)
- Tokimec (Japanese Text) version (ATA & ARPA)

The M4.08 release applies to the following systems:

- Single and Dual Channel Tactical Displays
- Special Features (VISION and NON-VISION)

The commercial ATA remains at V3.05

The Single Card EPA (L) remains at SC1.01

### **3. Ship's Manual 65800010B issue 3 : ammendments**

The following important amendments should be carried out to the above manual:

Chapter 3, page 3-4, para 1.3.7.

Change service code for X Band Elliptical Waveguide from 6803652 to 9037748.

Chapter 3, page 3-52, para 2.4.4.

Change service code for 220/240 Volt, 1 $\emptyset$  (50/60 Hz) from 91003758 to 91003757.

Chapter 6, page 6-156, para 4.1.

Change service code for 340 Med Res CRT from MA0001223 to MA00010223

Chapter 6, page 6-156, para 4.4

Change service code for 65847A PCB from 65847651 to 65847851

Chapter 6, page 6-158, para 4.6

Change service code for 10kW Magnetron from 91003015 to 910/3015

Chapter 6, page 6-160, para 4.9

Change service code for Memorycard Assembly from 65821622 to 65800602