SPERRY MARINE UK

Service Bulletin No. 32

Product: Various : Decca BridgeMaster II, C Plath

Subject: General Information 5

Decca BridgeMaster II Radars

1. CRT Drive & Base board PCBs kit 65620700

INCORRECT INSTRUCTIONS

When having to use the 65620816 Base Board, the Focus lead is a 'PUSH FIT' to the CRT Socket / Focus Assembly. NOT soldered as instructed.

2. 20" CRT Panasonic M48KHS794X11 (code 3034879) is obsolete

The above CRT is now replaced by type M48KTU104X08 but has the same code number. This tube requires revised field and scan coil connections. To order this CRT, do not use its code number. Instead, order modification DV 33 rev B. This mod contains the new CRT and instructions on re-wiring the yoke.

3. Memory Card & Battery

The part number for a BridgeMaster (I or II) Memory Card is 91003465. You should not use a BME memory card (MA00009233) as there is a good chance that it will not work.

The Battery replacement kit 65600712 is still common for all types of cards. Note there is a new procedure for replacing the batteries. See instructions supplied with the kit.

<u>C PLATH</u>

4. Service Bulletins & Manuals

There are now all Service Bulletins and certain Manuals from C PLATH in the New Malden Intranet Network. The path is as follows:

Uk-NML-03\data_1\service\Public\Technical Support\C Plath...

For local users : O:\service\Public\Technical Support\C Plath...