




SPERRY MARINE UK
Service Bulletin No. 41

Product: Decca BridgeMaster E Series Radars

Subject: Processor Electronics Unit

When replacing either the Display Processor PCB or the Radar Processor PCB ensure the ribbon cable (65800521) is bent INWARDS and check that the PCBs remain parallel to each other. This will prevent the possibility of the lower PCB being bowed by the cable and thus stopping it shorting on the Power Supply cover.



Processor Electronics Unit