

SPERRY MARINE UK
Service Bulletin No.10 (Release 13)

Product: Service Bulletins

Subject: Index

SB No:	Release	Date	Product	Subject
1	1	Aug-99	BME	GPS Interfacing
1_add1	1	Sep-99	BME	NMEA Signal Inverter . Addendum 1 to SB 1
1_add2	1	Nov-99	BME	Summary of GPS Rxs Tested. Addendum 2 to SB 1
2	8	Aug-05	BME	Display Software/Hardware Compatibility Tables
3	1	Jan-00	BME	Installations without Compass. Law and Spike Setting
3_add1	1	Jan-00	BME	S Band Scanner Motor wiring. Addendum 1 to SB3
4	1	Apr-00	BME	Cursor Freeze & Graphics Reset Alarm
5	1	Nov-00	BME	BM E 'L' Series
6	1	Nov-00	BME	Serial Message, Tx COMMS & TX BIST Alarms
7	1	Nov-00	BME	AZI ERROR Alarms
8	2	Mar-01	BME	S Band TU Maintenance Schedule
9	3	Feb-05	BME	List of current Manuals
10	13	Aug-05	SBs	Service Bulletins Index (<i>this document</i>)
11	1	Mar-01	BME	S Band Motors/Gearboxes Matrix
12	3	Nov-02	BME	Fitting of Flash (Software) V3.xx
13	2	Mar-01	BME	TCU / SW 1-8 settings
14	6	Aug-05	BME	Modification Index
15	2	Feb-04	BME	General Information 1
16	1	May-01	BME	Graphics Reset Alarm
17	2	Mar-03	BME	Ancillary Units Software/Hardware Compatibility
18	1	Oct-01	BME	S Band Scanner Motor
19	1	Oct-01	BME	Degauss function fault finding
20	2	Nov-02	BME	Display Monitor Data
21	1	Jan-02	BME	'Vision' Option
22	1	Jan-02	BME	Removal/Replacement of S Band Scanner Motor
23	2	Mar-03	BME	Field Upgrade Kits
24	1	Jan-02	BME	Installation/Long Cable Runs
25	2	May-05	BME	Optimising Video Display and Tracking Performance
26	1	Jan-02	BME	General Information 2
27	1	Jul-02	Leica	Replacing the Digital Display
28	3	Mar-05	BME	Fitting of Flash (Software) V4.xx
29	1	Jul-02	BME	Software Version C4.08 & M4.08
30	1	Jul-02	BME	General Information 3
31	1	Jul-02	BME	General Information 4
32	1	Jul-02	BM2/Plath	General Information 5
33	1	Nov-02	BME	New ITU Regulations regarding 10kW Magnetrons
34	1	Nov-02	BME	Trigger PCB 65801806 Compatibility
35	1	Nov-02	BME	S Band Antenna Fixings Locking Tabs

SPERRY MARINE UK
Service Bulletin No.10 (Release 13)

SB No:	Release	Date	Product	Subject
36	1	Nov-02	BME	Interswitch Unit 65842A V2.0 Software
37	1	Nov-02	BME	Fitting of Flash (Software) version SC1.xx series
38	1	Nov-02	BME	Tokimec OEM versions
39	1	Nov-02	BM1/2	Software Compatibility Chart
40	1	Feb-03	BME	340 CRT type Monitors Important Information
41	1	Feb-03	BME	Processor Electronics Unit ribbon cable
42	5	Aug-05	BME	Fitting of Flash (Software) V5.xx
43	6	Aug-05	BME	Version 4.xx and 5.xx series Software
44	1	Mar-03	BME	Interswitch 65842A Bypass Instructions
45	1	Jun-03	BM1/2	X Band TU Final Drive & Intermediate Belts oversized
46	1	Jun-03	FMFS	General Information 1
47	2	May-05	BME	AIS Interface guidelines
48	1	Feb-04	Decca	Product Notice: Products no longer supported
49	1	Jan-04	BME	Advisory Notice: S Band Turning Units
50	1	Feb-04	BME	S Band Turning Units. Specification changes
51	2	Aug-04	BM/2490	General Information 6
52	1	Feb-04	BME	General Information 7
53	1	Feb-04	BME	CRT v FPD Compatibility Chart
54	2	Aug-05	BME	340 CRT to FPD Conversion
55	2	Mar-05	BME	General Information 8
56	1	Dec-04	BME	Spares Breakdown Booklet
57	1	Feb-05	BME	S Band Turning Unit Intermittent Azi Error
58	1	Feb-05	BME	Power Supply failure with FPD systems
59	1	Feb-05	BME	General Information 9
60	1	Mar-05	BME	General Information Index
61	1	May-05	BME/BM/S90	'CORE' Turning Units
62	1	May-05	BME	Unit Type Numbers and Labels
63	1	May-05	BME	Testing of Flat Panel Displays
64	1	May-05	BME/BM	Maps & Memory Cards
65	1	Aug-05	BME	Vision FT BME 340 Displays