SPERRY MARINE UK

Service Bulletin No. 45

Product: Decca BridgeMaster I & II Series Radars

Subject: X Band Turning Unit Final Drive and Intermediate Belts

IMPORTANT INFORMATION

Final Drive Belt part number MA00008128 Intermediate Belt part number MA00008110

Our supplier has recently advised us that their measurement of the above belts has been incorrect for some considerable time. They are generally oversized and will cause slippage either immediately after fitting or certainly shortly after.

ALL CURRENT STOCK HELD IS SUSPECT (except warehouses GB0FC1 & NL0KB1)

Any stock supplied by Vlaardingen from now on will be correct.

The smallest Motor Drive Belt, part number MA00008102 is **OK**.

Action required by all Sperry Marine Service Depots and Service Representatives:

- Immediately return **ALL** current stock held to Sperry Marine in Vlaardingen, Holland by post. Depots should return by Transfer Order.
- Advise Sperry Marine in Vlaardingen, Holland of the number of belts requiring replacement (same numbers as returned).
- For urgent immediate requirements, place emergency (Code 1) order with Ship's name by the usual means.